O/o.Chief General Manager Telecom Transmission Planning Unit 5th Floor, 'B' Wing, BSNL Admin. Complex Juhu Road Santacruz(West), Mumbai-54 Tel.022-2646 7609 Fax, 022-2660 1161



भारत संचार निगम लिमिटेड

(नारत सरकार का उपक्रम)

BHARAT SANCHAR NIGAM LIMITED

(A Govt. of India Enterprise)

No.CGMT/MH/TP/Measuring Instrument/2021-22 (14

Dated21 .09.2021

To, All BA/SSA Heads MH. Telecom Circle

Sub; Measuring Instruments available with SSA.

Ref: BSNLCO-CNO/14/(13)/12021-CNO dated. 31.08.2021

This has ref to BSNL CO letter under ref, wherein it was requested to submit the net requirement for Measuring Instruments & report regarding the faulty testing equipment available with SSAs, with due action to get repaired the faulty units and unit which are beyond repair to get scrapped immediately.

In view of above, all SSAs are requested to get the faulty Measuring Instruments repaired & units which are beyond repair (RNP) be scapped immediately under intimation to this office, so that net requirement to be forwarded BSNL CO may be justified.

Status of availability of Measuring Instruments (faulty/Working) updated by SSA in Googal Sheet is enclosed for ref.


This is issued with the approval of GM (Trans/NOFN).

Encl. a/a

Dy. GM(Tx-NOFN)

O/o. CGMT, Mumbai-54

	ALC: U						1						
-		Measuring Instruments available in SSA (Field Unit/Store)											
	SI no	SSA .	Splicing Machine		Splicing Machine		OTDR ,		1		STM	DOM	
			(Normal)		(Ribbon Type)				Power Meter		1	PON	
-	0.110		Working Faulty								Analyser	OTDR	
				radity	WOLKING	Faulty	Working	Faulty	Working	Faulty			
	1	Ahmednagar	· 3	3									
	_2	Amravati	2	1	2	0	3	2.	2	1		1 .	
	3	Akola	1 .	5	1	0	0	1	1	0	0	0	
	4	Aurangabad	6	1	1	0		2	2	0	0	1	
	5	Beed	3	4	0	0	6	3	6	0	0	. 0	
	6	Bhandara	2	4	0	0;	1	4	1	0	0		
	7	Buldana	5	1	0	0,	2.	3	2	4	0	1	
	8	Chandrapur	2	1	1	0	1	2	2	1	0	1	
	9	Dhule	2	4	0	1	2	1	3	<u>1</u>	0	1	
L	10	Gadchiroli	2	1	0	0	0	2	0			2	
L	11	Goa	4	5	1	2	5	2	5	0	0	0	
	12	Jalgaon	3	3	1	1	3	3	2	2	0	0	
L	13	Jalna_	3	2	0	0	3	1	2	1	0 .	1	
L	14	Kalyan	8	1	1	0	9	1	4	2	0		
L	15	Kolhapur	4	2	1	0	4	2	4	1	0	0	
	16	Latur	2	1			1	. 1	2	1	-		
L	17	Nagpur	13	_ 5			10	5					
L	18	Nanded	4	2	1	0	3	• 3	2	1	1	1	
L	19	Nashik .	3	0	1	0	2	<u>1</u>	4	0	. 0	0	
L	20	Osmanabad	2 '	1	0	0	2	1	1		0	0	
	21	Parbhani	. 1	5	Ò	0	0	8	1	0	0	•1	
L	22	Pune	6	5	2	2	7	6	9	5	, 0	0	
L	23	Raigad	6	0	0	0	3	1	0	0	0	0	
L	24	Ratnagiri	2 .	. 2	0	0	2	2	1	1	0	. 0	
_	25	Sangli	3	2	1	1	2	2	2	1	0	1	
	26	Satara	2	1	0	0	2	1	1	1	0	0	
_	27	Sindhudurg	3	3	0	0	2	3	3	3	0	1	
_	28	Solapur	4	2	0	0	3	3	3	1	0	1	
$\overline{}$	29	Wardha	2	3	1	_0	2	1	1	2	0,	1	
	30	Yeotmal	3	2	0	1	2	2	0	2	0	1	
		Total	106	72	15	8	85	70	66	32	1		
										<u> </u>		15	



Core Network Operation Cell, 8th Floor, BSNL Bhawan, BSNL Corporate Office. New Delhi-110001 011-23711419 Fax 011-23329800



BHARAT SANCHAR NIGAM LIMITED

(A Govt. of India Enterprise)

F.N. BSNLCO-CNO/14(13)/1/2021-CNO

Dated 31,08,2021

To.

- All CGMs CN-Tx Circles/Mtce. Regions
- 2. CGMT, All Circles/telecom Districts.

Subject: Submission of net requirement of Transmission Network testing equipment against faulty/scrapped units for in-house maintenance of BSNL OFC routes (Splicing Machine, OTDR, Power Meter, Light Source etc.)-regarding.

Kindly refer to above cited subject, it is submitted that CNP Cell has processed the case of procurement of test instruments & splicing machines against the requirement received from your circle.

In this regard, PF Cell, BSNL CO has pointed out that procurement against faulty units cannot be justified. If repair is possible these should be got repaired and used, else if these equipment cannot be repaired & used these should be scrapped.

It is also noted that for certain items the total quantity available is more that the number justified by norms, and yet some quantities have been proposed for procurement. This needs to be rationalized and restricted to numbers justified as per norms. The circle wise list of requirement submitted for approval for procurement is enclosed for reference as Annexure.

In the view of above, it is requested to kindly get repaired the faulty units and units which are beyond repair may got scrapped immediately.

Accordingly revised requirement as per format enclosed as Annexure may kindly be submitted to CNO Cell by 07.09.2021 for further processing the case.

This is issued with the approval of competent authority.

Encl.:A/a

(Narender Kumar)

DGM(CNO)

To, ITOGP)

Dem (TP)

Requirement of Transmission Testing Equipments

S.N.	Name of Circle/Region	ltem	Item TYPE		N	NET Requirement (post Scrapping,				
					Total FAUETY	Working	Faulty Item details		outsourcing of	
								scrapped/	Repaired/	O&M)
		1					Total	to be	Under-	
								scrapped	repair	
			Single Fibre	225	201	121	80	25	47	
1		SPLICING MACHINE	Ribbon Type	225	201	121		u	N.	
1	MH Circle	MINI OTDR		225	155	85	70	N	54	
		OTDR TYPE-1	-					14	•	
19		PON OTDR COMBO			15	15	0	1	-	
1		POWER Meter			98	66	32	6	26	
1		LIGHT SOURCE			66	32	34	3	61	
		ANY OTHER								